





**GIRAFFE**  
ME1014



It is highly recommended that you visit [www.metalearth.com/360/ME1014](http://www.metalearth.com/360/ME1014) to see the completed model before assembling your own



## TO CREATE THE BEST CONNECTIONS



### Legends:

- E** Engraved/ Color side
- NE** Non - engraved/ Silver side
- Attention point
- Insert tab and bend 90 degrees
- Insert tab and twist 90 degrees

### Assembly tip:

If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish.

- Yellow areas should be curled
- Red areas should be folded


In order to avoid possible injury from sharp edges, please carefully discard the metal sheets after parts have been removed.

### Recommended tools:


- Wire cutters: helpful for taking parts from the metal sheets.




- Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.



## METAL SHEETS






Parts with same color are duplicates




## ASSEMBLY FLOW CHART

### Step 1













Step 2











Step 3








Step 7





Step 8




Step 9



Step 10



Step 11



Step 12

